PCT/CA99/01100

WO 01/39353

FIG.-1

44554

STD


UT


LT


СТ


**UMB** 

1/6











PCT/CA99/01100


WO 01/39353


FIG. 2

2/6









THE THE PERSON NAMED IN COLUMN TO SERVICE AND ADDRESS OF THE PERSON NAMED IN COLUMN T

09/889642


PCT/CA99/01100

WO 01/39353

FIG. 3

3/6







UMH with Center Tandem Motor UMH + CT = UT



17









UMH with Lower Tandem Motor UMH + LT = STD









1 613 828 0024 P.16/21 09/889642


PCT/CA99/01100

WO 01/39353

FIG. 4


4/6





WO 01/39353

PCT/CA99/01100



And the state of t

PCT/CA99/01100

WO 01/39353

6/6

FIG. 6

